

704 Park Street (Commercial Building)  
Hartford  
Hartford County  
Connecticut

HABS No. CT-427

HABS  
CONN,  
2-HARE,  
17-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY  
MID-ATLANTIC REGION, NATIONAL PARK SERVICE  
DEPARTMENT OF THE INTERIOR  
PHILADELPHIA, PENNSYLVANIA 19106

HABS  
CONN,  
2-HARF,  
17-

ARCHITECTURAL DATA FORM

STATE Connecticut	COUNTY Hartford	TOWN OR VICINITY Hartford
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) 704 Park Street		HABS NO. CT- 427
SECONDARY OR COMMON NAMES OF STRUCTURE Commercial Building		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 704 Park Street, Hartford, CT 06106		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1890 (Hartford Land Records, vol. 214, p. 581)	ARCHITECT(S) (INCLUDE SOURCE) Unknown Builder: Edward Brady	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Brady built the house as a residential investment property, for himself. It is a late but good example of a red-brick Italianate-style house, of which there were many in Hartford. The segmental lintels connected by a string course of recessed brick are typical of the work of Hartford's 19C masons.		
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick bearing walls with frame interior structure.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) See sketch.		
EXTERIOR FEATURES OF NOTE The store front and brick and cinder-block additions completely encircle the house. The enlarged structure occupies approximately the entire parcel.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The first floor of the house has been removed. Second floor is not accessible. The front part of the building still has restaurant fixtures in it. The large rear section, formerly a dance hall, is vacant.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES The first addition was the store front, in 1912. Others followed. The 95-foot rear section was constructed in 1951.		
PRESENT CONDITION AND USE Condition is badly deteriorated. Building is vacant.		
OTHER INFORMATION AS APPROPRIATE Had the interior conditions been known at the time of preparation of the National Register nomination, the structure would not have been designated as Contributing.		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Hartford Land Records, building permits, city atlases of 1866, 1880, 1896, 1909, 1917, Frog Hollow National Register Historic District nomination.		
COMPILER, AFFILIATION David F. Ransom, Consultant		DATE October 31, 1988

